

RAS KITS

Lap Steel Guitar Kit



Inspect all pieces to be that they are present and in working order. If for some reason there is a missing or defective part, you can contact our Customer Response Team at

customerservice@rasdistributors.com

1. You want to complete a dry fit of all the pieces to ensure all holes are the proper size and pre-drilled holes are in proper location.
2. After completing your dry fit, you will complete your finishing process on the body of the guitar, fingerboard, etc...any piece that you want to paint or stain. The finishing process is outside the scope of these instructions but there are a wide variety of resources online.
3. Begin assembly by starting with the tuning machines. Be sure that the knobs are facing up when tuning machines are inserted. Secure the tuning machines with 8 screws provided.




4. Secure the nut to the body with 2 screws provided.



- Secure the fingerboard to the body with the 8 screws provided.



- Wire the pickup to the pots and output jack. Reference the wiring diagram below.



RAS GUITAR KITS

- Solder the bridge ground wire to the volume pot and place under bridge before securing. Secure the bridge with 5 screws provided.



8. Secure pots and output jack with washers and nuts provided.



9. Secure cavity cover to back of the body.



Congratulations! You have completed the Lap Steel Guitar Kit build. If there is anything we can do to be of assistance, please let us know at customerservice@rasdistributors.com.

RAS KITS